

From first power-on to OS booting: software solutions for hardware issues


October 2016



Elite Software R&D Services
Since 1990


Device development

Typical design flow



In the beginning

Reference platform




Device under development ("10 differences")


PINMUXes, GPIOs, CLKs, etc:

	A	B	C	D	E	F
1	1 MDC0 Pin	GPIO Pin	Pin	Function	GPIO Pin	Pin
2	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
3	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
4	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
5	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
6	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
7	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
8	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
9	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
10	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
11	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
12	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
13	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
14	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
15	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
16	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
17	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
18	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
19	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
20	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
21	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
22	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
23	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
24	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
25	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
26	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
27	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
28	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
29	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin
30	GPIO Pin	Pin	Pin	GPIO Pin	Pin	Pin

PowerOn



- Leds are on
- Voltages are OK
- Clocks are generated
- POR sequence is correct
- No smoke!



Boot



Engineer's tools


UART as “window into the world”



JTAG as “last hope”




GPIO bit-banging



System Boot


Boot mode



- NOR Flash
- NAND Flash
- SD/MMC/eMMC
- USB
- UART (“**BOOTME**”!)
- SPI/I2C (NOR, EEPROM)
- ...

System Boot

Typical booting sequence



1. OnChip ROM detects boot source
2. OnChip ROM reads intermediate bootloader into OnChip RAM and transfers control to it
Or
OnChip ROM reads configuration into OnChip RAM, initializes RAM, loads and runs main bootloader
3. SPL initializes RAM, loads and runs main bootloader
4. Main bootloader loads OS

Intermediate bootloader

Common name

SPL – **S**econdary **P**rogram **L**oader

Other names (Vendor specific):

IBL (Intermediate Boot Loader)

UBL (User Boot Loader)

X-loader (External Loader)

...


Features:

- Open source (Vendor provided)
- Executing in OnChip RAM
- Small size (OnChip RAM)

Main functions:

- Memory Controller and RAM initialization
- Loads main bootloader

RAM test



Bootloader

Alternatives:

- U-Boot (ARM, x86, ...)
- RedBoot (ARM, x86, ...)
- PMON2000 (MIPS, PowerPC)
- PRIME (MIPS)
- ...

Capabilities:

- Open source
- Simple configuring (GUI, menuconfig)
- Monitor functions (memory r/w, devices)
- Extensibility (new functionality)
- Scripting (U-Boot, RedBoot)
- Client applications (HW tests)


U-Boot: adaptation

Typical actions:

- Choose platform (board)
- Configure (make board_config)
- Build (make)
- Prepare bootable image (UART, MMC, ...)
- First boot
- Check first boot results
- Adjust and reconfigure
- Debug
- Add new platform (board)

U-Boot: adaptation


U-Boot calls sequence partial breakdown: (i.MX51 Babbage board)



U-Boot: enhancement

Add new driver


Allwinner A10 DISP driver
Linux kernel 3.0.8



1MB (97 files) sources in total

U-Boot


Calls sequence



900KB (55 files) sources in total


OS: porting Linux

Kernel sources



OS: porting Linux

First steps




1. `arch/arm/mach-<soc>`,
`<soc> = imx, davinci, pxa, ...`
2. `make menuconfig`,
Kernel hacking ->
Kernel low-level debugging port/functions
Early printk
3. Update platform source (2.6)
or
Update DTS (3.0, ...):
`arch/arm/boot/dts/<soc>-<platform>.dts`
4. `earlyprintk=tty<uart_name><num>`,
`<uart_name> = S, O, mxc, ...`
`<num> = 0, 1, 2, ...`
boardid: `arch/arm/tools/mach-types` (2.6)

OS: porting Linux

Kernel booting issues




No kernel messages



- Check UART settings and configuration platform (2.6) / DTS (3.0, ...)
- Enable early debug:
arch/arm/boot/compressed/**head.S**
arch/arm/mach-<soc>/include/mach/**debug-macro.S** (2.6)
or
arch/arm/boot/compressed/**debug.S** (3.0, ...)
Макросы:
addruart
senduart
busyuart
waituart

OS: porting Linux

Kernel successfully booted



Linux: kernel backporting

Reasons ?

- Customer requirements (particular version is needed)
- Support (driver updates)
- Security (fix vulnerabilities)
- ???

Linux: kernel backporting

From 3.0.35 to 2.6.34



i.MX 6Dual based board

Requirements


Vendor BSP

Kernel **2.6.34**

Kernel **3.0.35**

arch/arm, include, drivers, kernel, init, mm

Patch 40M



OS: Linux instead of Android ?



Would it be possible to install Linux instead of stock Android ?

Specific software


Requirements:

- Linux (any distro)
- GUI (X11)


OS: Linux instead of Android ?

Solution

30-pin connector



- Interface 0 ?
- Interface 1 ?
- ...
- Interface n ?



- USB OTG !**
- ...
- UART RXD/TXD !**
- ...



USB host-USB client-UART cable



Steps



1. UART + null-modem cable
2. Boot to Recovery
3. Root !
4. mmcblk0p0, mmcblk0p1, ...
5. USB flash drive
6. `dd if=/dev/block/mmcblk0 of=/usbdrive/emmc.img`
7. `emmc.img => GPT => p0, p1, p2, ... => p2 boot image (kernel + ramdisk) !`
8. Download kernel sources (vendor provided)
9. OpenEmbedded + kernel sources => `bzImage` + `rootfs`
10. `mkbootimg: bzImage + ramdisk => bootimg`
11. UART, USB flash drive, Recovery: `dd if=/usbdrive/bootimg of=/dev/block/mmcblk0p2`
12. Kernel is booted !

OS: Linux instead of Android ?


Results

GPE

Boot splash



Login



Features

- Angstrom distro
- x11-gpe-image
- No multitouch is supported (modified TS-driver)
- Rootfs on USB drive (root=/dev/sda1)


Hardware issues

Possible causes

- Design errors
- Routing errors
- Mounting issues
- Component defects
- Components errors (Errata, workarounds)
- ~~Physical damages~~
- ~~Incompatible conditions~~

Hardware issues

Common approach: troubleshooting and looking for solution



1. Suspected HW-issue
2. Localization failing source code.
3. HW test
("three-lines program").
4. HW issue confirmed ?
5. No.
Caused by SW.
6. Yes.
Can be bypassed by SW ?
7. Yes.
Working out solution and add it to sources
8. Further accordingly to results
(Fail or Success).

Hardware issues

Software solution


Workaround

From Wikipedia, the free encyclopedia

A workaround is a bypass of a recognized problem in a system.


A workaround is typically a temporary fix that implies that a genuine solution to the problem is needed.

But workarounds are frequently as creative as true solutions, involving outside the box thinking in their creation.



Software solution: workaround


Spontaneous device power on



Caused by ?


PowerOn bounce

The solution
was implemented
in bootloader
(U-Boot)




Software solution: workaround

Unstable device behavior





Software solution: workaround

CMOS camera1: black and white photos




Software solution: workaround

CMOS Camera2: autofocus frame is present on the photos




Software solution: workaround

LCD: the leftmost column issue





Software solution: workaround

Resistive touchscreen: false pressings



Software solution: reimplementation

ASIC video controller:
incorrectly working hardware BitBlt with OR




The solution
was implemented
in driver



Symbols displaying was
implemented with hardware
BitBlt with XOR.


Software solution: reimplementation

RTC Alarm reboot



Software solution: not found


About design errors



Due to erroneous design actual traffic rate turned out to be half the level of anticipated.
The bottle neck was FPGA <-> FPGA section.
This issue doesn't have a software solution.

Hardware issue ?

SD HC vs SD Host 1.01



This is not hardware issue!

In accordance with SD Spec. 2.0 SDHC cards shall execute CMD8 (Send Interface Condition) after CMD0 (Go Idle State) and before ACMD41 (Send Operation Condition) during card initialization.

Minor driver fix allowed to work with SDHC card on SD Spec. 1.01 host controller.

Contacts



Thank You

Auriga, USA

92 Potter Rd, Ste. 1
Wilton, NH 03086, USA
Phone: +1 (866) 645-1119
Fax: +1 (603) 386-6097
info@auriga.com
www.auriga.com

Auriga, Russia

125 Varshavskoe Shosse, Unit 16A,
Moscow, 117587
Tel: +7 (495) 713-9900
Fax: +7 (495) 939-0300
info@auriga.com
www.auriga.com



Elite Software R&D Services
Since 1990